

VERIFICATION OF EMC COMPLIANCE

Verification No.: GZEM2005012683HSVR
Applicant: Beijing Holtop Air Conditioning Co., Ltd.
Address of Applicant: Building 1-7, No. 5 Yard, 7th Guanggu Street, Kangzhuang Town, Yanqing District, Beijing, China.
Manufacturer: The same as applicant
Address of Manufacturer: The same as applicant
Factory: The same as applicant
Address of Factory: The same as applicant
Product Description: Energy Recovery Ventilator
Model No.: Please refer to page2 for details
Sufficient samples of the product have been tested and found to be in conformity with
Test Standard(s): EN 55014-1:2017
EN 55014-2:2015
EN IEC 61000-3-2:2019
EN 61000-3-3:2013+A1:2019

As shown in the

Test Report Number(s): GZEM200501268301

This verification of EMC Compliance has been granted to the applicant based on the results of the tests, performed by laboratory of SGS-CSTC Standards Technical Services Co., Ltd. on the sample of the above-mentioned product in accordance with the provisions of the relevant specific standards under Directive 2014/30/EU.

The CE mark as shown below can be used, under the responsibility of the manufacturer, after completion of an EU Declaration of Conformity and compliance with all relevant EU Directives.



Kobe Jian
EMC Laboratory Manager



Date: 2021-04-22

VERIFICATION OF EMC COMPLIANCE

Verification No.: GZEM2005012683HSVR

Model No.:

XHBQ-D1.5DMTHA, XHBQ-D2.5DMTHA, XHBQ-D3.5DMTHA, XHBQ-D1.5DCTPA, XHBQ-D2.5DCTPA, XHBQ-D3.5DCTPA;
XHBQ-D5DMTHA, XHBQ-D6.5DMTHA, XHBQ-D8DMTHA, XHBQ-D10DMTHA, XHBQ-D13DMTHA, XHBQ-D15DMTHA, XHBQ-D20DMTHA, XHBQ-D26DMTHA, XHBQ-D5DCTPA, XHBQ-D6.5DCTPA, XHBQ-D8DCTPA, XHBQ-D10DCTPA, XHBQ-D15DCTPA, XHBQ-D20DCTPA, ERVQ-D150-2A1D, ERVQ-D150-2B1D, ERVQ-D150-2A2D, ERVQ-D150-2B2D, ERVQ-D250-2A1D, ERVQ-D250-2B1D, ERVQ-D250-2A2D, ERVQ-D250-2B2D, ERVQ-D350-2A1D, ERVQ-D350-2B1D, ERVQ-D350-2A2D, ERVQ-D350-2B2D, ERVQ-D600-2A2D, ERVQ-D600-2B2D, ERVQ-D500-2C2D, ERVQ-D500-2D2D, ERVQ-D800-2A2D, ERVQ-D800-2B2D, ERVQ-D650-2C2D, ERVQ-D650-2D2D, ERVQ-D10H-2A2D, ERVQ-D10H-2B2D, ERVQ-D800-2C2D, ERVQ-D800-2D2D, ERVQ-D13H-2A2D, ERVQ-D13H-2B2D, ERVQ-D10H-2C2D, ERVQ-D10H-2D2D, ERVQ-D13H-2C2D, ERVQ-D13H-2D2D, ERVQ-D15H-2C2D, ERVQ-D15H-2D2D, ERVQ-D20H-2C2D, ERVQ-D20H-2D2D, ERVQ-D26H-2C2D, ERVQ-D26H-2D2D;
XHBQ-D2DCTHC, XHBQ-D1.5DCTFC, XHBQ-D3DCTHC, XHBQ-D2.5DCTFC, XHBQ-D4DCTHC, XHBQ-D3.5DCTFC, XHBQ-D2DCPMTHC, XHBQ-D1.5DMTHC, XHBQ-D3DCPMTHC, XHBQ-D2.5DMTHC, XHBQ-D4DCPMTHC, XHBQ-D3.5DMTHC;
ERVQ-D150-2B1, ERVQ-D150-2A1C, ERVQ-D150-2B1C, ERVQ-D150-2A2C, ERVQ-D150-2B2C, ERVQ-D250-2B1, ERVQ-D250-2A1C, ERVQ-D250-2B1C, ERVQ-D250-2A2C, ERVQ-D250-2B2C, ERVQ-D350-2B1, ERVQ-D350-2A1C, ERVQ-D350-2B1C, ERVQ-D350-2A2C, ERVQ-D350-2B2C, XHBQ-D6DCTHC, ERVQ-D600-2A2C, ERVQ-D500-2C2C, XHBQ-D5DCTFC, XHBQ-D8DCTHC, ERVQ-D800-2A2C, ERVQ-D650-2C2C, XHBQ-D6.5DCTFC, XHBQ-D10DCTHC, ERVQ-D10H-2A2C, ERVQ-D800-2C2C, XHBQ-D8DCTFC, XHBQ-D13DCTHC, ERVQ-D13H-2A2C, ERVQ-D10H-2C2C, ERVQ-D13H-2C2C, XHBQ-D10DCTFC, XHBQ-D13DCTFC, XHBQ-D15DCTHC, ERVQ-D15H-2C2C, XHBQ-D15DCTFC, XHBQ-D20DCTHC, ERVQ-D20H-2C2C, XHBQ-D20DCTFC, XHBQ-D26DCTHC, ERVQ-D26H-2C2C, XHBQ-D26DCTFC, XHBQ-D6DCPMTHC, ERVQ-D600-2B2C, ERVQ-D500-2D2C, XHBQ-D5DMTHC, XHBQ-D8DCPMTHC, ERVQ-D800-2B2C, ERVQ-D650-2D2C, XHBQ-D6.5DMTHC, XHBQ-D10DCPMTHC, ERVQ-D10H-2B2C, ERVQ-D800-2D2C, XHBQ-D8DMTHC, XHBQ-D13DCPMTHC, ERVQ-D13H-2B2C, ERVQ-D10H-2D2C, ERVQ-D13H-2D2C, XHBQ-D10DMTHC, XHBQ-D13DMTHC, XHBQ-D15DCPMTHC, ERVQ-D15H-2D2C, XHBQ-D15DMTHC, XHBQ-D20DCPMTHC, ERVQ-D20H-2D2C, XHBQ-D20DMTHC, XHBQ-D26DCPMTHC, ERVQ-D26H-2D2C, XHBQ-D26DMTHC;